ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
3

Ward Name
Atturu

Street ID
W0218, W0220, W0222, W0365, W0359, W0248, W0373, W

Street Name
NA, Chikka Muniswammappa Lyt, 2nd Crs, East Park Reje Lyt, Ambedkar Nagar Slum, Dr Ambekdar Govt Ash

Significant Landmark
yelahanaka 4th phase, SFS 407,SFS 208, SFS 707 mai

Segment No.
3/C-W0218/S083752

Total Length (m)
936.89

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	147.18	77.572931	13.106141	77.574277	13.105974	W0373	W0383
2	193.07	77.572834	13.107949	77.572856	13.106204	W0226	W0246
3	230.71	77.572866	13.106084	77.573086	13.104010	W0246	W0270
4	115.01	77.570313	13.103474	77.571252	13.103357	W0359	W0365
5	136.06	77.569996	13.103853	77.571246	13.103746	W0365	W0357
6	114.86	77.571273	13.104070	77.571321	13.103033	W0270	W0222

Work Details

History of Road / Lane / Circles

Name of the Work
Providing asphalting to roads and Improvements to Drains in yelahanaka 4th phase, SFS 407,SFS 208, SFS 707 main and cross roads and some part of Anant

Sanctioned Estimated Amount (Rs.)
5000000

Sanctioned Year
2017

Year
2017 - 2018

Type of Work
Asphalting

Other Work Type

Tender
Not a Tender

Work Details
Providing asphalting to roads and Improvements to Drains in yelahanaka 4th phase, SFS 407,SFS 208, SFS 707 main and cross roads and some part of Ananthapura village in ward no 03 Yelahanka Satellite Town Sub division Yelahanka zone

Job No. / Work Code
003-17-000013

Work Order No.
BBMP/EE (YNK.D) /WO/145/2017 -18

Work Order Date
31/03/2017

Period of Extention
90 DAYS

Defect Liability Period From

Defect Liability Period To

Multiple road involved with the same Job No/ Work Code #

30/04/2017	29/04/2018	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	
9449863065		

Field Inspection Details

Number of Trees	Any Other Information	Name
16		CHANDRAKANTH
Date of Inspection	**Remarks**	
23/05/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Alluru **Street ID:** W0218, W0220, W0222, W0365,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	23/05/2017	22/06/2017	COMPLETED
SE	VASU K M	23/05/2017	22/06/2017	COMPLETED
EE	VASU K M	23/05/2017	22/06/2017	COMPLETED
AEE	ASHOK	23/05/2017	22/06/2017	COMPLETED
AE	CHANDRAKANTH	23/05/2017	22/06/2017	COMPLETED
AE	CHANDRAKANTH	23/05/2017	22/06/2017	COMPLETED

Zone: YELAHANKA

Ward No: 3

Ward Name: Atturu

Street ID: W0218, W0220, W0222, W0365,

AE-02

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಜಿ.ಬಿ.ಎ.ಎ.ಕ. ಬೆಂಗಳೂರು-106